


# RC Code IRDA-4807 not programmable

Protocol RC5 38KHz Code page - 14 (0xE)



From:  
<https://docs.infomir.com.ua/> -

Permanent link:  
[https://docs.infomir.com.ua/doku.php?id=en:stb\\_webkit:faq:rc\\_code\\_table](https://docs.infomir.com.ua/doku.php?id=en:stb_webkit:faq:rc_code_table)

Last update: **2019/05/17 11:23**

